

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2008 Levee Inspection Results

Reclamation District No. 1000

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1000**

Waterway		Bank	Unit Miles
Unit No. 01 Sacramento River		Left	18.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/10/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Sacramento River						Left	18.60	03/10/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.05	18.60	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.604677 ° -121.510330 °	38.806683 ° -121.657227 °		2
2	0.05	18.60	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.604697 ° -121.510275 °	38.761047 ° -121.721602 °		1
3	0.18	0.22	Earthen Levee	Encroachments	WS	PO	Landscaping	38.778408 ° -121.601488 °	38.777902 ° -121.601062 °		131
4	0.79	1.00	Earthen Levee	Rip Rap Revetments	WS	A		38.770933 ° -121.595685 °	38.768278 ° -121.593988 °		130
5	1.69	1.71	Earthen Levee	Encroachments	WS	PO	Landscaping	38.758697 ° -121.591178 °	38.758447 ° -121.591253 °		136
6	1.74	1.77	Earthen Levee	Encroachments	WS	PO	Landscaping	38.757962 ° -121.591342 °	38.757480 ° -121.591147 °		135
7	1.77	1.79	Earthen Levee	Encroachments	WS	PO	Landscaping	38.757478 ° -121.591140 °	38.757238 ° -121.591272 °		134
8	1.88	1.91	Earthen Levee	Encroachments	WS	PO	Landscaping	38.755975 ° -121.591433 °	38.755585 ° -121.591530 °		133
9	1.96	1.98	Earthen Levee	Encroachments	WS	PO	Landscaping	38.754848 ° -121.591742 °	38.754562 ° -121.591795 °		132
10	2.02	2.03	Earthen Levee	Encroachments	WS	PO	Landscaping	38.753983 ° -121.591737 °	38.753848 ° -121.591797 °		129
11	2.03	6.31	Earthen Levee	Encroachments	WS	PO	Landscaping	38.754067 ° -121.592585 °	38.754683 ° -121.593370 °		123
12	2.11	2.18	Earthen Levee	Encroachments	WS	PO	Landscaping	38.752513 ° -121.592017 °	38.751822 ° -121.592857 °		122
13	2.55	2.70	Earthen Levee	Encroachments	WS	PO	Landscaping	38.747087 ° -121.595582 °	38.745127 ° -121.596793 °		121
14	5.23	5.29	Earthen Levee	Encroachments	WS	PO	Landscaping	38.711248 ° -121.610500 °	38.710700 ° -121.611233 °		120
15	5.31	5.34	Earthen Levee	Encroachments	WS	PO	Landscaping	38.710508 ° -121.611450 °	38.710132 ° -121.611882 °		119
16	5.68	5.72	Earthen Levee	Encroachments	WS	CO	Landscaping	38.706593 ° -121.616155 °	38.706082 ° -121.616385 °		118
17	5.72	5.75	Earthen Levee	Encroachments	WS	PO	Landscaping	38.706085 ° -121.616385 °	38.705662 ° -121.616837 °		117
18	6.04	6.07	Earthen Levee	Encroachments	WS	PO	Landscaping	38.702742 ° -121.620557 °	38.702467 ° -121.620947 °		116
19	6.20	6.22	Earthen Levee	Encroachments	WS	PO	Landscaping	38.701422 ° -121.622755 °	38.701120 ° -121.623063 °		113

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 Sacramento River							Left	18.60	03/10/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	6.22	6.24	Earthen Levee	Encroachments	LS	PO	Fences	38.701178 ° -121.623060 °	38.700947 ° -121.623370 °		114
21	6.22	6.24	Earthen Levee	Encroachments	LS	PO	Landscaping	38.701177 ° -121.623057 °	38.700950 ° -121.623375 °		115
22	6.22	6.25	Earthen Levee	Encroachments	WS	CO	Landscaping	38.701120 ° -121.623065 °	38.700822 ° -121.623468 °		112
23	6.36	6.39	Earthen Levee	Encroachments	WS	CO	Landscaping	38.699877 ° -121.624948 °	38.699575 ° -121.625475 °		111
24	6.41	6.47	Earthen Levee	Encroachments	WS	PO	Landscaping	38.756757 ° -121.596252 °	38.757943 ° -121.599515 °		124
25	6.43	6.47	Earthen Levee	Encroachments	WS	PO	Landscaping	38.699237 ° -121.626088 °	38.698907 ° -121.626617 °		110
26	6.49	6.49	Earthen Levee	Encroachments	WS	PO	Landscaping	38.758607 ° -121.601933 °	38.758607 ° -121.601933 °		125
27	6.58	6.61	Earthen Levee	Encroachments	WS	PO	Landscaping	38.697958 ° -121.628273 °	38.697773 ° -121.628682 °		109
28	6.61	6.70	Earthen Levee	Encroachments	WS	PO	Landscaping	38.697775 ° -121.628685 °	38.696618 ° -121.629425 °		108
29	6.76	6.78	Earthen Levee	Encroachments	WS	PO	Landscaping	38.695892 ° -121.630053 °	38.695642 ° -121.630353 °		107
30	6.88	6.89	Earthen Levee	Encroachments	WS	PO	Landscaping	38.694348 ° -121.631007 °	38.694187 ° -121.631200 °		106
31	6.89	6.92	Earthen Levee	Encroachments	WS	PO	Landscaping	38.694192 ° -121.631203 °	38.693932 ° -121.631470 °		105
32	6.92	6.95	Earthen Levee	Encroachments	WS	PO	Landscaping	38.693935 ° -121.631478 °	38.693412 ° -121.631765 °		104
33	6.99	7.03	Earthen Levee	Encroachments	WS	PO	Landscaping	38.693043 ° -121.632048 °	38.692553 ° -121.632373 °		103
34	7.03	7.07	Earthen Levee	Encroachments	WS	PO	Landscaping	38.692535 ° -121.632423 °	38.691872 ° -121.632490 °		102
35	7.10	7.16	Earthen Levee	Encroachments	WS	PO	Landscaping	38.691422 ° -121.632585 °	38.690707 ° -121.632842 °		101
36	7.16	7.18	Earthen Levee	Encroachments	WS	PO	Landscaping	38.690678 ° -121.632840 °	38.690367 ° -121.632797 °		100
37	7.22	7.27	Earthen Levee	Encroachments	WS	CO	Landscaping	38.689753 ° -121.632788 °	38.689077 ° -121.633003 °		99
38	7.36	7.36	Earthen Levee	Encroachments	WS	PO	Landscaping	38.687808 ° -121.632495 °	38.687808 ° -121.632495 °		98

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 Sacramento River							Left	18.60	03/10/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	7.36	7.36	Earthen Levee	Encroachments	WS PO	Landscaping		38.687808 ° -121.632495 °	38.687808 ° -121.632495 °		97
40	7.39	7.43	Earthen Levee	Encroachments	WS PO	Landscaping		38.687347 ° -121.632433 °	38.686780 ° -121.632138 °		96
41	7.66	7.72	Earthen Levee	Encroachments	WS PO	Landscaping		38.683620 ° -121.631180 °	38.682742 ° -121.631190 °		95
42	7.72	7.75	Earthen Levee	Encroachments	WS PO	Landscaping		38.682742 ° -121.631168 °	38.682310 ° -121.631085 °		94
43	7.81	7.86	Earthen Levee	Encroachments	WS PO	Landscaping		38.681592 ° -121.630768 °	38.680837 ° -121.630530 °		93
44	8.08	8.11	Earthen Levee	Encroachments	WS PO	Landscaping		38.678023 ° -121.628670 °	38.677672 ° -121.628432 °		92
45	8.18	8.19	Earthen Levee	Encroachments	WS PO	Landscaping		38.676893 ° -121.627860 °	38.676747 ° -121.627725 °		91
46	8.22	8.25	Earthen Levee	Encroachments	WS CO	Landscaping		38.676425 ° -121.627462 °	38.676038 ° -121.627063 °		90
47	8.25	8.28	Earthen Levee	Encroachments	WS PO	Landscaping		38.676040 ° -121.627063 °	38.675772 ° -121.626785 °		89
48	8.36	8.38	Earthen Levee	Encroachments	WS PO	Landscaping		38.674830 ° -121.625830 °	38.674610 ° -121.625652 °		88
49	8.38	8.42	Earthen Levee	Encroachments	WS PO	Landscaping		38.674607 ° -121.625655 °	38.674117 ° -121.625143 °		87
50	8.56	8.59	Earthen Levee	Encroachments	WS PO	Landscaping		38.672878 ° -121.623203 °	38.672603 ° -121.622892 °		86
51	8.60	8.66	Earthen Levee	Encroachments	WS PO	Landscaping		38.672487 ° -121.622783 °	38.671790 ° -121.622118 °		85
52	8.77	8.86	Earthen Levee	Encroachments	WS CO	Landscaping		38.670647 ° -121.620632 °	38.669790 ° -121.619482 °		84
53	8.96	8.98	Earthen Levee	Encroachments	WS PO	Landscaping		38.668898 ° -121.618195 °	38.668672 ° -121.617775 °		83
54	8.98	9.02	Earthen Levee	Encroachments	WS CO	Landscaping		38.668673 ° -121.617772 °	38.668405 ° -121.617278 °		82
55	9.03	9.08	Earthen Levee	Encroachments	WS PO	Landscaping		38.668312 ° -121.617138 °	38.667783 ° -121.616382 °		81
56	9.09	9.11	Earthen Levee	Encroachments	WS PO	Landscaping		38.667672 ° -121.616215 °	38.667552 ° -121.616018 °		80
57	9.11	9.14	Earthen Levee	Encroachments	WS PO	Landscaping		38.667505 ° -121.615912 °	38.667255 ° -121.615525 °		79

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway							Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Sacramento River							Left	18.60	03/10/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue	
	Start	End						Start	End			
58	9.15	9.17	Earthen Levee	Encroachments	WS PO	Landscaping		38.667250 ° -121.615522 °	38.667028 ° -121.615115 °		78	
59	9.17	9.21	Earthen Levee	Encroachments	WS PO	Landscaping		38.667022 ° -121.615105 °	38.666620 ° -121.614580 °		77	
60	10.07	10.20	Rivers, Channels & Designated Floodways	Rip Rap Revetments	WS	A		38.657782 ° -121.603972 °	38.656167 ° -121.602707 °		76	
61	10.34	10.36	Earthen Levee	Encroachments	LS PO	Landscaping		38.654508 ° -121.601280 °	38.654332 ° -121.601097 °		75	
62	10.88	10.92	Earthen Levee	Encroachments	WS CO	Landscaping		38.648127 ° -121.595872 °	38.647663 ° -121.595483 °		74	
63	10.95	10.99	Earthen Levee	Encroachments	WS CO	Landscaping		38.647373 ° -121.595248 °	38.646825 ° -121.594800 °		73	
64	11.23	11.30	Earthen Levee	Encroachments	WS PO	Landscaping		38.644548 ° -121.591768 °	38.644302 ° -121.590572 °		72	
65	11.33	11.38	Earthen Levee	Encroachments	WS	Landscaping		38.644313 ° -121.590088 °	38.644338 ° -121.589222 °		71	
66	11.42	11.51	Earthen Levee	Encroachments	WS CO	Landscaping		38.644393 ° -121.588498 °	38.644702 ° -121.586992 °		70	
67	11.84	11.88	Earthen Levee	Encroachments	WS CO	Landscaping		38.647408 ° -121.582090 °	38.647773 ° -121.581423 °		69	
68	12.21	12.60	Earthen Levee	Encroachments	LS PO	Landscaping		38.650302 ° -121.576493 °	38.649125 ° -121.569563 °		63	
69	12.25	12.29	Earthen Levee	Encroachments	LS CO	Buildings		38.650315 ° -121.575622 °	38.650367 ° -121.575005 °		68	
70	12.33	12.44	Earthen Levee	Encroachments	WS PO	Landscaping		38.653208 ° -121.573895 °	38.650245 ° -121.572188 °		66	
71	12.35	12.62	Earthen Levee	Encroachments	WS PO	Landscaping		38.650867 ° -121.573877 °	38.648223 ° -121.569630 °		67	
72	12.44	12.55	Earthen Levee	Encroachments	WS PO	Landscaping		38.651785 ° -121.571670 °	38.649560 ° -121.570438 °		65	
73	12.55	12.59	Earthen Levee	Encroachments	WS PO	Landscaping		38.649533 ° -121.570387 °	38.649253 ° -121.569810 °		64	
74	12.59	12.64	Earthen Levee	Encroachments	WS CO	Landscaping		38.649253 ° -121.569815 °	38.648895 ° -121.569043 °		62	
75	12.64	12.67	Earthen Levee	Encroachments	WS PO	Landscaping		38.648897 ° -121.569030 °	38.648588 ° -121.568467 °		61	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 Sacramento River							Left	18.60	03/10/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
76	12.72	12.77	Earthen Levee	Encroachments	WS	CO	Landscaping	38.648172 ° -121.567843 °	38.647738 ° -121.567167 °		60
77	12.77	12.85	Earthen Levee	Encroachments	WS	CO	Landscaping	38.647665 ° -121.567045 °	38.646812 ° -121.566135 °		59
78	12.89	12.98	Earthen Levee	Encroachments	WS	CO	Landscaping	38.646400 ° -121.565695 °	38.645302 ° -121.564733 °		58
79	13.04	13.04	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.644543 ° -121.564332 °	38.644543 ° -121.564332 °		57
80	13.08	13.08	Earthen Levee	Encroachments	WS	PO	Landscaping	38.644028 ° -121.563823 °	38.644028 ° -121.563823 °		56
81	13.12	13.13	Earthen Levee	Encroachments	WS	PO	Landscaping	38.643527 ° -121.563518 °	38.643378 ° -121.563402 °		55
82	13.13	13.14	Earthen Levee	Encroachments	WS	PO	Fences	38.643380 ° -121.563400 °	38.643275 ° -121.563307 °		54
83	13.18	13.24	Earthen Levee	Encroachments	WS	PO	Landscaping	38.642740 ° -121.563030 °	38.641860 ° -121.562832 °		53
84	13.26	13.30	Earthen Levee	Encroachments	WS	PO	Landscaping	38.641620 ° -121.562753 °	38.641113 ° -121.562557 °		52
85	13.36	13.41	Earthen Levee	Encroachments	WS	PO	Landscaping	38.640205 ° -121.562370 °	38.639540 ° -121.562238 °		51
86	13.47	13.51	Earthen Levee	Encroachments	WS	PO	Landscaping	38.638668 ° -121.562085 °	38.638065 ° -121.562015 °		50
87	13.51	13.55	Earthen Levee	Encroachments	WS	PO	Landscaping	38.638067 ° -121.562013 °	38.637600 ° -121.561932 °		49
88	13.55	13.58	Earthen Levee	Encroachments	WS	CO	Landscaping	38.637602 ° -121.561930 °	38.637060 ° -121.561833 °		48
89	13.58	13.62	Earthen Levee	Encroachments	WS	CO	Landscaping	38.637052 ° -121.561833 °	38.636527 ° -121.561743 °		47
90	13.62	13.64	Earthen Levee	Encroachments	WS	PO	Landscaping	38.636522 ° -121.561743 °	38.636250 ° -121.561667 °		46
91	13.68	13.70	Earthen Levee	Encroachments	WS	PO	Landscaping	38.635638 ° -121.561570 °	38.635387 ° -121.561497 °		45
92	13.70	13.72	Earthen Levee	Encroachments	WS	CO	Landscaping	38.635390 ° -121.561490 °	38.635032 ° -121.561482 °		44
93	13.86	13.90	Earthen Levee	Encroachments	WS	CO	Fences	38.633238 ° -121.561097 °	38.632590 ° -121.560915 °		43
94	14.21	14.24	Earthen Levee	Encroachments	WS	CO	Landscaping	38.628300 ° -121.560180 °	38.627873 ° -121.560202 °		42

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway							Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 Sacramento River							Left	18.60	03/10/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue	
	Start	End						Start	End			
95	14.31	14.32	Earthen Levee	Encroachments	WS PO	Landscaping		38.626905 ° -121.560062 °	38.626863 ° -121.561015 °		41	
96	14.37	14.39	Earthen Levee	Encroachments	WS PO	Landscaping		38.625975 ° -121.560127 °	38.625642 ° -121.560185 °		39	
97	14.38	14.52	Earthen Levee	Encroachments	WS CO	Landscaping		38.625807 ° -121.560390 °	38.623812 ° -121.561345 °		40	
98	14.79	14.82	Earthen Levee	Encroachments	WS PO	Landscaping		38.620077 ° -121.560120 °	38.619630 ° -121.560067 °		38	
99	14.85	14.90	Earthen Levee	Encroachments	WS CO	Landscaping		38.619112 ° -121.560113 °	38.618493 ° -121.560070 °		37	
100	14.92	14.92	Earthen Levee	Encroachments	WS PO	Landscaping		38.618163 ° -121.560113 °	38.618163 ° -121.560113 °		36	
101	14.98	15.02	Earthen Levee	Encroachments	WS PO	Landscaping		38.617388 ° -121.559970 °	38.616835 ° -121.559807 °		35	
102	15.33	15.38	Earthen Levee	Encroachments	WS CO	Landscaping		38.612555 ° -121.558258 °	38.611900 ° -121.558303 °		34	
103	15.46	15.48	Earthen Levee	Encroachments	WS PO	Fences		38.610787 ° -121.557817 °	38.610455 ° -121.557638 °		33	
104	15.50	15.52	Earthen Levee	Encroachments	WS PO	Fences		38.610180 ° -121.557453 °	38.609908 ° -121.557328 °		32	
105	15.54	15.57	Earthen Levee	Encroachments	WS CO	Landscaping		38.609743 ° -121.557252 °	38.609315 ° -121.557000 °		31	
106	15.70	15.73	Earthen Levee	Encroachments	WS CO	Landscaping		38.607715 ° -121.555847 °	38.607345 ° -121.555538 °		30	
107	15.74	15.82	Earthen Levee	Encroachments	WS CO	Fences		38.607207 ° -121.555465 °	38.606255 ° -121.554582 °		29	
108	15.85	15.87	Earthen Levee	Encroachments	WS PO	Landscaping		38.605915 ° -121.554290 °	38.605687 ° -121.554070 °		28	
109	15.88	15.91	Earthen Levee	Encroachments	WS PO	Landscaping		38.605585 ° -121.553983 °	38.605273 ° -121.553663 °		27	
110	15.91	15.93	Earthen Levee	Encroachments	WS PO	Landscaping		38.605265 ° -121.553647 °	38.605032 ° -121.553437 °		26	
111	15.93	15.97	Earthen Levee	Encroachments	WS PO	Landscaping		38.605002 ° -121.553413 °	38.604598 ° -121.553008 °		25	
112	16.01	16.01	Earthen Levee	Encroachments	WS PO	Landscaping		38.604075 ° -121.552568 °	38.604075 ° -121.552568 °		24	
113	16.09	16.10	Earthen Levee	Encroachments	WS PO	Landscaping		38.603083 ° -121.551690 °	38.602943 ° -121.551593 °		23	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 Sacramento River							Left	18.60	03/10/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
114	16.11	16.13	Earthen Levee	Encroachments	WS	PO	Landscaping	38.602870 ° -121.551598 °	38.602617 ° -121.551330 °		22
115	16.14	16.16	Earthen Levee	Encroachments	WS	PO	Landscaping	38.602517 ° -121.551248 °	38.602373 ° -121.550963 °		2
116	16.20	16.23	Earthen Levee	Encroachments	WS	PO	Fences	38.601977 ° -121.550473 °	38.601678 ° -121.550142 °		20
117	16.30	16.33	Earthen Levee	Encroachments	WS	PO	Landscaping	38.600988 ° -121.549198 °	38.600665 ° -121.548795 °		19
118	16.34	16.36	Earthen Levee	Encroachments	WS	PO	Landscaping	38.600525 ° -121.548640 °	38.600397 ° -121.548447 °		18
119	16.80	16.86	Earthen Levee	Encroachments	LS	M	Agricultural Ditch	38.601810 ° -121.541572 °	38.602302 ° -121.540823 °		17
120	16.86	16.90	Earthen Levee	Encroachments	WS	CO	Fences	38.602328 ° -121.540788 °	38.602688 ° -121.540157 °		16
121	16.90	16.95	Earthen Levee	Encroachments	WS	PO	Fences	38.602693 ° -121.540165 °	38.603092 ° -121.539490 °		15
122	16.97	17.00	Earthen Levee	Encroachments	WS	PO	Fences	38.603242 ° -121.539318 °	38.603597 ° -121.538875 °		14
123	17.06	17.18	Earthen Levee	Encroachments	WS	PO	Fences	38.604188 ° -121.538027 °	38.604890 ° -121.536105 °		13
124	17.32	17.55	Earthen Levee	Encroachments	LS	A	Agricultural Ditch	38.605563 ° -121.533622 °	38.605590 ° -121.529582 °		12
125	17.64	17.74	Earthen Levee	Encroachments	WS	PO	Fences	38.605645 ° -121.527902 °	38.605542 ° -121.526112 °		11
126	17.77	17.82	Earthen Levee	Encroachments	WS	CO		38.605482 ° -121.525492 °	38.605447 ° -121.524678 °		10
127	17.82	17.91	Earthen Levee	Encroachments	WS	CO	Buildings	38.605445 ° -121.524675 °	38.605305 ° -121.522958 °		8
128	17.83	17.86	Earthen Levee	Encroachments	LS	CO	Buildings	38.605420 ° -121.524375 °	38.605462 ° -121.523852 °		9
129	17.91	17.94	Earthen Levee	Encroachments	WS	CO	Buildings	38.605300 ° -121.522957 °	38.605200 ° -121.522422 °		7
130	18.10	18.10	Earthen Levee	Encroachments	WS	CO	Buildings	38.604788 ° -121.519720 °	° °		6
131	18.10	18.18	Earthen Levee	Encroachments	WS	CO	Buildings	38.604758 ° -121.519610 °	38.604532 ° -121.518190 °		5
132	18.21	18.40	Earthen Levee	Encroachments	WS	CO	Buildings	38.604515 ° -121.517635 °	38.603918 ° -121.514370 °		4

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Sacramento River	Left	18.60	03/10/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
133	18.22	18.40	Earthen Levee	Encroachments	WS CO	Buildings		38.604418 ° -121.517538 °	38.603897 ° -121.514397 °		3

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1000**

Waterway		Bank	Unit Miles
Unit No. 02 American River		Right	2.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/19/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway						Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 American River						Right	2.30	03/19/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	2.33	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.605932 ° -121.470800 °	38.604932 ° -121.510000 °		4
2	0.00	2.33	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.605932 ° -121.470800 °	38.604932 ° -121.510000 °		3
3	0.07	2.30	Earthen Levee	Encroachments	LS	PO	Landscaping	38.604932 ° -121.510243 °	38.605932 ° -121.470770 °		1
4	1.50	1.70	Earthen Levee	Encroachments	WS	PO	Landscaping	38.607880 ° -121.484500 °	38.607110 ° -121.480950 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1000**

Waterway		Bank	Unit Miles
Unit No. 03 Natomas East Canal		Right	17.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/3/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 03 Natomas East Canal						Right	17.30	03/03/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.04	5.80	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.606547 ° -121.469932 °	38.684865 ° -121.485563 °		1
2	0.04	5.80	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.606547 ° -121.469932 °	38.684870 ° -121.485565 °		2
3	0.07	0.13	Earthen Levee	Encroachments	LS	PO	Fences	38.606882 ° -121.469480 °	38.607523 ° -121.469033 °		7
4	0.13	0.19	Earthen Levee	Encroachments	LS	CO	Fences	38.607522 ° -121.469033 °	38.608377 ° -121.468658 °		6
5	0.30	0.32	Earthen Levee	Encroachments	LS	PO	Fences	38.609865 ° -121.468183 °	38.610162 ° -121.468122 °		5
6	0.53	0.57	Earthen Levee	Encroachments	LS	PO	Fences	38.613077 ° -121.468133 °	38.613700 ° -121.468263 °		4
7	3.05	3.10	Earthen Levee	Encroachments	LS	PO	Fences	38.648677 ° -121.474882 °	38.649412 ° -121.475005 °		3
8	5.83	17.26	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.685383 ° -121.485388 °	38.820950 ° -121.543437 °		9
9	5.83	17.26	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.685375 ° -121.485382 °	38.820950 ° -121.543435 °		8

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2008 Levee Inspection Results
Reclamation District No. 1000**

Waterway		Bank	Unit Miles
Unit No. 04 Natomas Cross Canal		Left	4.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	3/7/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 1000

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 04 Natomas Cross Canal	Left	4.40	03/07/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.02	4.33	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.820522 ° -121.544060 °	38.781168 ° -121.603503 °		1
2	0.02	4.33	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.820523 ° -121.544057 °	38.781170 ° -121.603503 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected